

Radon Inspection Report

Measurement of Radon Concentration in Indoor Air

Report No.: 2700007005201806271701
Serial No.: 2700007005

Report Generated Date: 6/27/18

Measurement Address:
1234 E Main St.
Anytown , Oklahoma 12345
United States

Measurement performed by:
Steve Allison
OklaHome Inspections

Ventilation: Natural

Building type: House

Building year: 1970

Room	Floor	Measurement Start	Measurement End	Measured Value
Bed room	Ground floor	6/25/18, 5:37 PM	6/27/18, 4:37 PM	0.6 pCi/L

Comments:

Broken Arrow

June 27, 2018

Location

Date

Signature

Detailed Measurement Data


	Min	Max	Average
Radon [pCi/L]	0.0	3.9	0.6
Temperature [°F]	73.4	82.0	78.5
Humidity [%rH]	50	60	54
Pressure [kPa]	98.37	98.96	98.79

Table of hourly radon measurements for hour 1 to hour 47

Timestamp	Radon values
Hr: 1 - 6:37 PM	0.6
Hr: 2 - 7:37 PM	0.0
Hr: 3 - 8:37 PM	1.9
Hr: 4 - 9:37 PM	0.6
Hr: 5 - 10:37 PM	0.6
Hr: 6 - 11:37 PM	2.0
Hr: 7 - 12:37 AM	1.3
Hr: 8 - 1:37 AM	1.3
Hr: 9 - 2:37 AM	1.3
Hr: 10 - 3:37 AM	0.0
Hr: 11 - 4:37 AM	0.6
Hr: 12 - 5:37 AM	3.9
Hr: 13 - 6:37 AM	0.6
Hr: 14 - 7:37 AM	0.4
Hr: 15 - 8:37 AM	0.8
Hr: 16 - 9:37 AM	0.4
Hr: 17 - 10:37 AM	0.0
Hr: 18 - 11:37 AM	0.4
Hr: 19 - 12:37 PM	0.4
Hr: 20 - 1:37 PM	0.0
Hr: 21 - 2:37 PM	0.4
Hr: 22 - 3:37 PM	0.4
Hr: 23 - 4:37 PM	0.8
Hr: 24 - 5:37 PM	0.4

Timestamp	Radon values
Hr: 25 - 6:37 PM	0.0
Hr: 26 - 7:37 PM	0.3
Hr: 27 - 8:37 PM	0.0
Hr: 28 - 9:37 PM	0.0
Hr: 29 - 10:37 PM	0.6
Hr: 30 - 11:37 PM	0.3
Hr: 31 - 12:37 AM	0.0
Hr: 32 - 1:37 AM	0.6
Hr: 33 - 2:37 AM	0.6
Hr: 34 - 3:37 AM	1.2
Hr: 35 - 4:37 AM	0.3
Hr: 36 - 5:37 AM	1.1
Hr: 37 - 6:37 AM	1.2
Hr: 38 - 7:37 AM	0.8
Hr: 39 - 8:37 AM	1.2
Hr: 40 - 9:37 AM	0.4
Hr: 41 - 10:37 AM	0.4
Hr: 42 - 11:37 AM	0.0
Hr: 43 - 12:37 PM	0.0
Hr: 44 - 1:37 PM	0.8
Hr: 45 - 2:37 PM	0.0
Hr: 46 - 3:37 PM	0.0
Hr: 47 - 4:37 PM	0.4

Radon and Movement Chart



Humidity and Temperature Chart

